





## Parts List


**A** x 3

**B** x 3


Silver Screw









**C** x 12


Black Screw

**D** x 12

**E** x 12

## Installation Guide

**1**

**2**

**3**

**4**

**5**


### CAUTION

Please power off the PC and check the Positive and Negative ends on the connector before connecting the cable to mainboard. Connecting the wrong end can damage the fans.