





Parts List




Intel Installation Guide


1 ① 1200/115X ② 1954/1851 ③ 1366



2 1954/1851/1700/1366/1200/115X




3




NOTE : Apply the thermal paste evenly with a spatula **E** for better cooling performance.

4 1954/1851/1700/1366/1200/115X

2066/2011-3/2011




5




AMD Installation Guide


1




2




3



4




5





NOTE : Apply the thermal paste evenly with a spatula **E** for better cooling performance.

Installation Guide


1



2



3



CAUTION

Please power off the PC and check the Positive and Negative ends on the connector before connecting the cable to mainboard. Connecting the wrong end can damage the fans.